
















































































8002 Parts List (Included Welding rod is not listed)

















Image	Qty	Part No. and Description	More Info
	1	<b>5003-01</b> Plastic Welding Rod Organizer	
	1	<b>5003TC</b> Temperature Control Switch	
	1	<b>6012-P</b> 200W, 120V Element w/ US Plug	
	1	<b>6020</b> Temperature Control Switch - 115/230V	
	1	<b>6027HT</b> Standard Welding Tip	
	1	<b>6031</b> Tear Drop Welding Tip	
	1	<b>6049-02</b> Temperature Control Knob	
	2	<b>6049-03</b> Flow control valve with micro-fine needle	

















			
	1	<b>6049-04</b> 218 8A 250VAC Fuse	
	2	<b>6049-05</b> 1/4 in. tube X 10/32 Straight Fitting	
	2	<b>6049-06</b> 1/4 in. tube X 10/32 90-degree fitting	
	1	<b>6049-07</b> Inlet Receptacle with Switch and Fuse	
	1	<b>6050-NR1</b> Hot air all purpose tip	
	1	<b>6052-16</b> Number 6 non-insulated ring terminal	
	10.5	<b>6052-33</b> PUR tubing 1/4" Green	
	1	<b>6053N2-03</b> Straight push-connect tube fitting	

















			
	4	<b>6053N2-04</b> 90 deg push-connect tube fitting	
	1	<b>6053N2-07</b> Three-way ball valve	
	2	<b>6053N2-08</b> 90 deg Bulkhead push-connect	
	1	<b>6056-05</b> Air Manifold for Nitrogen Cart	
	1	<b>6056-06</b> Power Strip for Nitrogen Cart	
	1	<b>6056-07</b> Nitrogen Tank Regulator	
	1	<b>6056-08</b> MIG cart for Nitrogen Welder	
	1	<b>6056-11</b> 1/4" Galvanized Pipe Plug	

			
	2	<b>6056-12</b> 6" Gray Wheel w/bearings - Assembly	
	2	<b>6056-13</b> 2" Gray Casters w/brake 1.5" brass ring stem	
	2	<b>6056-14</b> Washers for cart	
	2	<b>6056-15</b> 1/2" Cap Nut Washer	
	1	<b>6057-02</b> Flow Gauge, 0-25 lpm	
	1	<b>6057-05</b> 15A Snap-in receptical	
	1	<b>6057-13</b> 1/8"F NPT to 1/4" tube push connect fitting	
	2	<b>6057-15</b> 1/8" M NPT to 1/4" tube push-connect fitting	













			
	1	<b>6057-17</b> Pressure Switch	
	1	<b>6057-19</b> Runtie Fitting	
	4	<b>6057-20</b> Rubber feet	
	10	<b>6057-28</b> 6 X 1/2" Hex washer head machine screw	
	4	<b>6057-30</b> 8 x 3/4" phillips pan head sheet metal screw	
	8	<b>6057-31</b> 1/8" x 1/8" grip steel rivet	
	2	<b>6057-33</b> 10-24 Hex Nylock Nut	
	2	<b>6057-34</b> 10-24 x 1-3/4" Machine Screw	

			
	2	<b>6057-35</b> 10 x 1-1/4 Hex Head Screw	
	4	<b>6057-37</b> 1/4" AMP (M) QD connector	
	3	<b>6057-38</b> 1/4" AMP (F) QD connector	
	1	<b>6057-39</b> Tube Connector 1/4" x 1.5mm orifice	
	1	<b>6062ME</b> Hot Air Element - 550 watt	
	45	<b>6066-09</b> 1/4"-20 x 1/2" Hex Bolt / Zinc	
	45	<b>6066-10</b> 6 mm Flat Washer / Zinc	
	1	<b>6066-30</b> Union Elbow	

			
	1	<b>6085-11</b> Female 1/8NPT x 1/4 HOSE 90 deg fitting	
	1	<b>6086-04</b> Straight 1/8" NPT x 4mm tube connector	
	1	<b>6102-02</b> Quick release hose	
	1	<b>6102-03</b> Bulkhead fitting for quick release hose	
	1	<b>6102-04</b> Welder handle connector assembly	
	1	<b>6124WB</b> Stainless wire brush	
	1	<b>6145</b> Hand Seamer	
	1	<b>6150-04</b> 6x3/8 SS oval head screw	

			
	1	<b>6150-06</b> Socket with Pins	
	2	<b>6086-06</b> Female bullet connector	
	1	<b>6151H-01</b> Quick Release Handle	
	1	<b>6151H-02</b> 4-40 x 3/16" Stainless Steel Set Screw	
	1	<b>6175-01</b> Stainless steel barrel	
	1	<b>6175-02</b> Brass nut for hot air barrel	
	1	<b>6482</b> Aluminum Tape, 2" x 10 yd	
	1	<b>CHAIN</b> Chains to secure nitrogen bottle	



			
	1	<b>CORD6-USA</b> USA Power Cord	
	1	<b>LIGHT4</b> Green Indicator light, 12mm	
	1	<b>NUT M6</b> Nut, Hex, 6-32,	
	2	<b>RIV2</b> 3/16 inch rivet	
	3	<b>RIV2</b> 1/4" SDS-84 Steel Blind Rivet	
	1	<b>STUD</b> Grounding stud	